

Tool & Product Update

**SUBJECT: "1976: configuration Model 200 H.I.T
Engineering changes designed to improve the reliability of the Model 200
Installation Tool have been incorporated beginning with serial number
5600.**

The *Shift Valve* and *Check Valve "A"* has been completely redesigned to eliminate *Shift Piston "creep"*. The *Pull Piston* has been redesigned to provide a hydraulic balance between the pull and return sides, virtually eliminating the tendency of the tool to "*pick up*" air. A collector tube has been added to the filler port in the handle to trap air above the hydraulic fluid inlet.

A program was set up at HUCK INTERNATIONAL, Installation Equipment Division, to modify earlier tools to the 1976 configuration. Tools so modified, will be identified by "1976" stamped near the serial number. The tools that are returned will be updated, painted and provided with a **NEW TOOL WARRANTY**. If other parts are required, due to wear or abuse they will be billed at current published prices. Contact Huck International, Installation Equipment Division for current charge for conversion. A 1976 conversion kit is ***not*** available because the head assembly of the tool requires additional machining and cleaning operations. Individual components are available for tools manufactured after serial number 5600 and for those that have been retrofitted.

Return tools with transportation charges prepaid to :
HUCK INTERNATIONAL
ATTN: REPAIR DEPARTMENT
85 GRAND STREET
KINGSTON NEW YORK, 12401
TELEPHONE 914-331-7300
FAX NUMBER 914-334-7333

Tools will be repaired and returned F.O.B. KINGSTON N.Y. Transportation charges will be **COLLECT** or **PREPAID AND ADDED** to your invoice as a separate item.

Questions regarding the 1976 configuration may be addressed to **CUSTOMER SERVICE** at the above address.

Revised
01-21-92
165